Declassified in Part - Sanitized Copy Approved for Release 2013/11/20 : CIA-RDP67B00329R000100130041-5

50X1

CLASSIFIED MESSAGE

S-E-C-R-E-T

ORIG: [redacted]
UNIT: OSA/COMMO
EXT: [redacted]
DATE: 13 AUGUST 1963

ROUTING			
1	COMMO	9	AIOS &
2	"	10	TAD
3	OEL	11	50X1
4	"	12	
5	INTEL	13	
6	DDA	14	50X1
7	OTECH	15	50X1
8	RB	16	

PRECEDENCE					INITIALS
	DEFERRED	XX	PRIORITY		
	ROUTINE		OPERATIONAL IMMEDIATE		INITIALS

TO: KWCARD [redacted]

FROM: DIRECTOR

CONF: OSA 1-15

INFO:

[redacted]

50X1

OUT15553

TO PRITY CARD [redacted] INFO

CITE ADIC 1535

HBJAYWALK COMMO ELINT ~~LOGS~~

REF: A. CARD 0053 (IN 87032) *

B. [redacted]

1. [redacted]

DOCUMENT NO. _____
NO CHANGE IN CLASS. X
☐ DECLASSIFIED
CLASS. CHANGED TO: TS S C
NEXT REVIEW DATE: 2011 50X1
AUTH: HR 70-2
DATE: 6/9/81 REVIEWER: 064540 50X1

2. RE PARA 3 REF A, AND PARA 1 REF B, MOD KITS FOR ELIMINATING AIC-10 NOISE FROM TIMING CHANNELS HAVE BEEN COMPLETED AND ARE ENROUTE TO KWCARD FOR INSTALLATION. MODIFICATION IS RELATIVELY SIMPLE, INVOLVING SEVERAL NEW COMPONENTS AND ONE REPLACEMENT COMPONENT. INSTALLATION TIME EXPECTED TO BE APPROX 1 HOUR. FUNCTION OF MOD WILL BE TO PREVENT AIC-10 TONES FROM FEEDING BACK TO RECORDER THROUGH SYSTEM XII. CIECUIT DIAGRAMS, INSTEUCTIONS, AND EXPLANATION WILL ACCONPANY MOD KITS FROM SYSTEM XII CONTRACTOR.

END OF MESSAGE

*Ref A requested info on the new System XII mod for eliminating AIC-10 noise from timing channel.

REF B indicated that analysts still having trouble reading timing tones, and queried what action taken to correct situation.

50X1
50X1

MD/OSA [redacted]
COORDINATING OFFICERS

[redacted]
CHIEF, OSA/COMMO
Rreleasing officer

S-E-C-R-E-T

GROUP 1
Excluded from automatic downgrading and declassification

AUTHENTICATING OFFICER

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. Copy No. 5

Declassified in Part - Sanitized Copy Approved for Release 2013/11/20 : CIA-RDP67B00329R000100130041-5